



Our ref: CEO 18754129
Your ref: HW/AD/105259

Helen Whately MP
House of Commons
London
SW1A 0AA

Nick Harris
Operations Executive Director
Bridge House
Walnut Tree Close
Guildford
Surrey
GU1 4LZ

nick.harris@highwaysengland.co.uk

7 June 2018

Dear Helen Whately

Resurfacing on the Brenley Corner roundabout

Thank you for your letter of 17 May to Jim O'Sullivan, on behalf of your constituent [REDACTED] concerning the resurfacing of Brenley Corner roundabout. I am replying to you as this issue falls within my area of responsibility.


The resurfacing works were completed on 5 May 2018. However, we were unable to resurface the bridge sections of the roundabout over the M2, due to a delay with design planning.

There is currently a scheme to renew and upgrade the lighting on the Brenley Corner roundabout, and we are looking to incorporate the outstanding resurfacing works into this scheme. The bridge sections of the roundabout have not been highlighted as a safety risk, but we will continue to monitor the area.

In our most recent inspection of 29 May, we identified one safety defect. A temporary repair was undertaken within 24 hours and a permanent repair is scheduled for 14 June. The next inspection is scheduled for 5 June.

If you would like any further information, please contact the Service Delivery Manager, Merwin Man who will be pleased to respond. He can be contacted by email at Merwin.Man@highwaysengland.co.uk or by telephone on 0300 470 1429. Alternatively our correspondence address is Bridge House, Walnut Tree Close, Guildford, Surrey GU1 4LZ.

Yours sincerely



Nick Harris
Operations Executive Director

www.highwaysengland.co.uk